

Vehicle Diagnostic Report

Repair Shop

Shop Name:Forreal ke

Address:

Zip Code:

Telephone:

Email:

SN:985197377300

Test Time:2026-03-07 13:39:47

Technician Name:Joan

Customer Name:ENGJAP



Vehicle Information

Year:2019

Make:Subaru

Model:Forester

Odometer:36602 km

Vehicle Software Version:V26.50

Diagnostic Application Version:V2.00.027

Diagnostic path:Automatically Search(Japan) > Forester > SK A(19MY)

System fault code

The following systems is abnormal:

Engine Control Module(ECM) 2 problems exist

1.P1604 Startability Malfunction

The past

2.P1603 Engine Stall history

The past

Transmission Control Module(TCM) 1 problem exist

1.P1603 Engine Stall history

The past

Anti-lock Braking System(ABS) 2 problems exist

1.C1921 Parking Position Switch Circuit

The past

2.C1923 Auto Vehicle Hold Switch Circuit

The past

Body Control Module(BCM) 1 problem exist

1.U0156 Lost Communication With Information Center A

The past

Supplemental Inflatable Restraint System(SRS) 3 problems exist

- 1.B16C2 Open in Pedestrian Airbag Temperature Sensor The past
- 2.B1683 Lost Communication With Pressure Sensor LH The past
- 3.B1687 Lost Communication With Pedestrian Airbag Pressure Sensor RH The past

Air Conditioning(AC) 3 problems exist

- 1.B14A1 Sunload Sensor Circuit Low Open Current
- 2.U0156 Lost Communication With Information Center A The past
- 3.U0457 Invalid Data Received From Information Center A The past

EyeSight(ES) 2 problems exist



- 1.B281E RAB Control Module The past
- 2.B281C Incompatible with EyeSight (EPS) The past

Automatic Light and Wiper(ALW) 3 problems exist

- 1.B2401 Sensor Installation Incorrect The past
- 2.B2406 A/S signal The past
- 3.B2407 Rain sensor temperature The past

Instrument cluster(IC) 1 problem exist

- 1.U0156 Lost Communication With Information Center A The past

Reverse Automatic Braking(RAB) 6 problems exist

- 1.B2C06 RR Sonar Sensor Circuit / No Signal The past
- 2.B2C08 RRC Sonar Sensor Circuit / No Signal The past
- 3.B2C0A RL Sonar Sensor Circuit / No Signal The past
- 4.B2C0C RLC Sonar Sensor Circuit / No Signal The past
- 5.B2C22 Eyesight System The past
- 6.U0156 Lost Communication With Information Center A The past

The following systems are OK:

- 1.EOBD
- 2.Power Steering(PS)
- 3.Keyless Access with Push Button Start(SMT)
- 4.Multi-function Display(MFD)
- 5.Headlight / Foglight(LT)
- 6.Power Seat Memory(SEAT)
- 7.Power Window (Driver)(PWD)
- 8.Power Window (Passenger)(PWP)
- 9.Power Window (Switch)(PWS)